

Building Safety Certificate

To whom so ever it may Concern

This is to certify that **Ahinsa International School (Run by: Ahinsa Foundation)** located at survey no 313/2B/2, Near Govt Agricultural College, Dhule Road, Nandurbar, Taluka & Dist-Nandurbar, Maharashtra, is running in a pucca building. I have personally inspected the entire school premises and building and verified RCC drawings on 05/03/2020.

Entire School campus found surrounded with pucca boundary wall. Entire school campus possesses adequate facilities and safety condition to run Secondary School.

I am of the opinion that the Building is safe enough for the purpose of running the school.

Place:- Nandurbar

Date:- 07/03/2020



Asst. Engineer, Gr.I
P.W.Subdivision No.1,
Taloda

जा. क्र./547 सन २०२०
सहाय्यक अभियंता, श्रेणी-१
सा. बां. उपविभाग, तळोदा ;
दिनांक- ०९ / ०३ / २०२०